OPERATING INSTRUCTIONS

• Plug in AC line cord.

 Before each use of electric desoldering tool, coat heated TIP with a layer of solder.

Press the plunger until it reaches the locked position.

 Place the TIP on component lead wire or IC lead from which solder is to be removed.

 Move tool in slightly circular motion until solder completely melts.

 Press the button to remove solder, Make sure all solder is removed.

 Periodically clean the pump by taking it out and unscrewing the bottom cover.

 Periodically replace the grease on the Piston inside the pump.

